east Mt. Henderson
Beartooths
MT
**Elevation:** 9450 ft
**Aspect:** 95°
**Specifics:** Collapsing, localized; We skied slope

Beau Fredlund
11/12/2022 - 11:00am
**Co-ord:**
**Slope Angle:** 29°
**Wind Loading:**

**Stability:**
**Air Temperature:**
**Sky Cover:** CLR
**Precipitation:** NO
**Wind:** Calm

**HS:**90

**Layer Notes:**
**27-0cm:** Problematic layer




**Notes:** Snowpit location was in a relatively wind sheltered area. Above the snowpit location, much of the east facing terrain was significantly wind affected/ 1F s
recent storm and not optimal for skiing. It seemed like all other aspects around the Mt. Henderson area (S, W and N) had less surface wind affect.

No avalanche activity observed.

Advisory Region
Cooke City
Longitude
-109.95W
Latitude
45.05N
**Avalanche Details:** Large collapses near Cooke City
Cooke City, 2022-11-13